C-47

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/Institute/SZ/2026/ 119 Dated: 30/07/2026

FIRE SAFETY CERTIFICATE

Certified that the M/s Institute of Sanskrit & Vedic Studies at Plot no.-3, Phase-II, Institutional Area, Vasant Kunj, New Delhi-70, was granted Fire Safety Certificate by this department vide letter no. F6/DFS/MS/Instt./2022/SZ/43 dated 28/01/2022 for two blocks- Institutional block- Basement + Ground + 03 upper floors & Hostel Block- Basement + Ground + 02 upper floors. The building was re-inspected by officer concerned of this department on 13/07/2026 in the presence of Dr. R. Vittobachar (Manager) and found that the building is now comprised of Two Blocks: - Institutional block- Basement + Ground + 03 upper floors & Hostel Block- Basement + Ground + 03 upper floors. The building has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises/building is fit for occupancy of Group B "Educational Building" (Institute) with effect from .....30/07/2026 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on...30/07/2026.at New Delhi by

30/7/26

(A.K. Malik)
Chief Fire Officer
Delhi Fire Service

Copy to:-

28/7/26

1. The Joint Director, (L &I) DDA, Building Section, Vikas Sadan, INA, New Delhi.
2. The Authorized Signatory, Institute of Sanskrit & Vedic Studies at Plot no.-3, Phase-II, Institutional Area, Vasant Kunj, New Delhi-70.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

2/28

INSPECTION REPORT					
1	Name & address of the building		**M/s Institute of Sanskrit & Vedic Studies at Plot no.-3, Phase-II, Institutional Area, Vasant Kunj, New Delhi-70.**		
2	Building is comprised of		**Comprised of Two Blocks: -** **Institutional block-** Basement + Ground + 03 upper floors **Hostel Block-** Basement + Ground + 03 upper floors		
3	Type of occupancy		Group B- Educational Building (Institute)		
4	Type of case		Renewal (addition/alternation of 3rd floor in existing building of Hostel block		
5	Details of previous FSC		F6/DFS/MS/Instt./2022/SZ/43 dated 28/01/2022		
6	Fire safety direction letter no.		F6/DFS/MS/BP/2002/2496 dated 26/12/2002		
7	Date of inspection		13/07/2026		
8	Name of the inspecting officers		Rajesh Kumar Shukla, ADO (Jangpura)		
9	Name of the designation of officer from the building side		Dr. R. Vittobachar (Manager)		
10	Year of construction		2014		
11	Applicant's letter no.		Online application no. 52026021601071		
S.No	**Minimum standard of fire prevention and fire safety U/R 33**		**Requirement**	**Provided at site**	**Remarks MR/NMR**
1	**Access to Building:**				
	A	Road width	9.0 m	Provided	MR
	B	Gate width	5.0 m	6.0 m	MR
	C	Width of internal road	NA	NA	NA
2	**Number, Width, Type and Arrangement of Exits:**				
	A	Number of staircases			
		a Upper floor	Block 1- 1 no. Block 2 – 2 nos.	Block 1- 2 nos. Block 2 – 2 nos.	MR
		b Basement	Block 1- 3 nos. + 1 ramp Block 2 – 2 nos.	Block 1- 3 nos. + 1 ramp Block 2 – 2 nos.	MR
	B	Width of staircases			
		a Upper floor	Block 1- 1.50 m, 0.75 m Block 2 – 1.50 m each	Block 1- 1.50 m & 1.35 m Block 2 – 1.50 m each	MR
		b Basement	1.50 m each	Block 1- 1.50 m each + 4.10 to 5.8 m ramp Block 2 – 1.50 m each	MR
	C	Protection of exits			
		a Fire check door	Required	Provided	MR
		b Pressurization	NA	NA	NA
	D	No. of continuous staircases to terrace	01 no. each block	2 nos. each block	MR
	E	Width of corridor	1.50 m each block	Provided	MR
	F	Door size	1.0 m	1.0 m	MR
3	**Compartmentation:**				
	A	Fire check door	NA	NA	NA
	B	Sealing of electrical shafts	NA	NA	NA
	C	Fire rating of shaft door	NA	NA	NA
	D	Water curtain	NA	NA	NA
	E	Fire dampers	NA	NA	NA
4	**Smoke Management System:**				
	A	Basement	Required	Provided	MR
	B	Upper floor	NA	NA	NA
5.	**Fire Extinguisher:**				
	A	Total numbers	20 nos.	22 nos.	MR
	B	Types	CO_2& ABC	CO_2& ABC	MR
	C	ISI marking	ISI Mark	Provided	MR
6	**First-Aid-Hose Reel:**				
	A	Total numbers of **each floor**	02 nos. each block	02 nos. each block	MR
	B	Length of hose reel hose	30 m	30 m	MR
	C	Nozzle diameter	5 mm	5 mm	MR

7	**Automatic Fire Detection and Alarming System:**				
	A	Type of detectors	Required	Provided	MR
	B	Location of main panel	Required	Provided	MR
	C	Location of repeater panel	NA	NA	NA
	D	Alternate source of power	Required	Provided	MR
	E	Hooters	Required	Provided	MR
8	**MOEFA:**		Required	Provided	MR
9	**Public Address System:**		NA	NA	NA
10	**Automatic Sprinkler System:**				
	A	Basement	Required	Provided	MR
	B	Upper floor	NA	NA	NA
	C	Sprinkler above false ceiling	NA	NA	NA
11	**Internal Hydrants:**				
	A	Size of riser/**down-comer**	100 mm each block	Provided	MR
	B	Number of hydrants per floor	1 no. each block	Provided	MR
	C	Hose box	1 no. each block	Provided	MR
12	**Yard Hydrants:**				
	A	Total number of hydrants	3 nos.	Provided	MR
	B	Hose box	3 nos.	Provided	MR
13	**Pumping Arrangements:**				
A	**Ground level**				
	a)	Discharge of main pump	2850 LPM	Provided	MR
	b)	Head of main pump	75 m	Provided	MR
	c)	Number of main pumps	1 no.	Provided	MR
	d)	Jockey pump out put	180 LPM	Provided	MR
	e)	Jockey pump head	75 m	Provided	MR
	f)	Standby pump out put	2850 LPM	Provided	MR
	g)	Standby pump head	75 m	Provided	MR
	h)	Auto starting /manual stopping	Required	Provided	MR
	i)	Pump house access	Required	Provided	MR
B	**Terrace Level**				
	a)	Discharge of pump	900 LPM	Provided	MR
	b)	Head of the pump	40 m	Provided	MR
	c)	Power supply	Required	Provided	MR
	d)	Auto starting of pump	Required	Provided	MR
14	**Captive Water Storage for Fire Fighting:**				
	A	Underground tank capacity	1,00,000 ltrs	Provided	MR
	B	Draw-off connection	Required	Provided	MR
	C	Fire service inlet	Required	Provided	MR
	D	Access to tank	Required	Provided	MR
	E	Overhead tank capacity	20,000 ltrs	20,000 ltrs + 7,500 ltrs	MR
15	**Exit Signage:**		Required	Provided	MR
16	**Provision of Lifts:**				
	A	Pressurization of lift shaft	NA	NA	NA
	B	Pressurization of lift lobby	NA	NA	NA
	C	Communication in lift car	NA	NA	NA
	D	Firemen's grounding switch	NA	NA	NA
	E	Lift signage	NA	NA	NA
17	**Standby Power Supply:**		Required	Provided	MR
18	**Refuge Area:**				
	A	Total area	NA	NA	NA
	B	Location	NA	NA	NA

N/30

19	**Fire Control Room:**				
	A	Detector system panel	NA	NA	NA
	B	Flow switch panel	NA	NA	NA
	C	PA system panel	NA	NA	NA
	D	Battery backup	NA	NA	NA
	E	Building floor plans	NA	NA	NA
20	**Special Fire Protection systems for protection of special Risks, if any:**		NA	NA	NA

LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

Note:- In the previous inspection report the building is comprised of two blocks namely **Institutional block-** Basement + Ground + 03 upper floors & **Hostel Block-** Basement + Ground + 02 upper floors while during inspection dated 13/07/2026 and it was observed that 3rd floor has been added to the Hostel block and now the Hostel block building is comprised of Basement + Ground + 03 upper floors. Thus, this is a case of addition/alteration hence inspection has been conducted as per DFS Act 2007 & Rules 2010.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If agreed to the note above & in view of the compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/Instt./2022/SZ/43 dated 28/01/2022 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

14/7/26

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (Jangpura)

DO (South)

1) Please clearly whether Hostel and Health Centre is same for which goods this have been DFS w.r.t. 28/12/2002.

15/7/26

ADO/JP

Ravinder Singh

Yes, Drawing D-7 placed on file clearly indicates that Hostel and Health Centre block are same. Health centre is located at Ground floor as per the plan while the upper Three floors are used as Hostel. Guidelines for B+G+3 upper floors have already been issued vide letter no. F6/DFS/MS/BP/2002/2496 dated 26.12.2022, however the last floor (3rd floor) has been recently added and all fire safety measures have been extended to the 3rd floor & are meeting the requirements. Submitted pls

17/7/26

DO (SD)

20/7/26

27/7/26

A.K. MALIK

CFO to [illegible]

CFO/SZ

Ravinder Singh

20/7/26

A.K. MALIK

22/7/26

CFO (SZ)