# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
# HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/ECN/2026/634 Dated :10./07./2026

## FIRE SAFETY CERTIFICATE

Certified that **M/s Sandoz Restaurant Pvt. Ltd.** located at **N-7, Ground Floor, N-Block, Connaught Place, New Delhi - 110001** in a building comprised of Ground, Mezzanine and 02 Upper Floor but **Restaurant running at Ground Floor and Mezzanine Floor is being used for Storage Purpose only** was earlier issued **Fire Safety Certificate** by this department vide letter No. **F6/DFS/MS/EH/NDZ/2023/148 dated 11.05.2023.** Now, the premises was re-inspected by the officer concerned of this department on **15/06/2026** in the presence of **Sh. Umesh Sharma, Manager** and found that the said building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class – **Assembly Occupancy for Restaurant at Ground Floor Only** with effect from 10/07/2026 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ....10/07/2026.....at New Delhi by.

9/7/26

**(Dr. S. K. Tomar)**
Chief Fire Officer
Delhi Fire Service

**Copy to: -**

1. The Chairman, NDMC, Palika Kendra, Parliament Street, New Delhi – 110001.: w.r.t. Online ID: - 2026053007712 dated 30/05/2026.
2. The Manager, Sandoz Restaurant Pvt. Ltd., N-7, Ground Floor, N-Block, Connaught Place, New Delhi - 110001.

**Conditions for the validity of Fire Safety Certificate**

1. **This FSC is valid for Restaurant at Ground Floor only.**
2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
3. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
4. The trained firefighting staff should be available round the clock.
5. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry.
10. Any flammable material for interior decoration is prohibited.

N/20

| INSPECTION REPORT | | | | |
|---|---|---|---|---|
| 1. | Name & address of the building | M/s Sandoz Restaurant Pvt. Ltd., N-7, G. und Floor, N-Block, Connaught Place, New Delhi - 110001. | | |
| 2. | Type of occupancy | Assembly Occupancy - Eating House (Restaurant) | | |
| 3. | Building is Comprised of | Ground + Mezzanine + 02 Upper Floors<br>**Restaurant running at Ground Floor and Mezzanine Floor is being used for Storage Purpose only** | | |
| 4. | Type of case | **Renewal** | | |
| 5. | Details of previous FSC No.: - | F6/DFS/MS/EH/NDZ/2023/148 dt. 11.05.2023 | | |
| 6. | Fire safety directives No.- | N/A | | |
| 7. | Date of inspection: - | 15/06/2026 | | |
| 8. | Name of the inspecting officer: - | Sh. Bhupender Prakash, ADO(ND) | | |
| 9. | Name & designation of officer From the building side: - | Sh. Umesh Sharma, Manager | | |
| 10. | Year of construction: - | Old Heritage | | |
| 11. | Applicant's letter No: - | MCD Online ID 2026053007712 dated 30/05/2026 | | |
| **S. No.** | **Minimum Standards on fire Prevention and fire safety U/R** | **Requirement/ Existing fire safety arrangements** | **Provided at site** | **Remarks MR/NMR** |
| 1. | **Access to Building** | | | |
| | • Road width | 6.00 mtr. | 20.00 mtr. | MR* |
| | • Gate width | N/A | N/A | N/A |
| | • Width of internal road | N/A | N/A | N/A |
| 2. | **Number, Width Type & Arrangement of Exits** | | | |
| | **a. Number of staircases** | | | |
| | • Upper floors (Mezzanine) | 02 nos. | 02 nos. | MR* |
| | • Basements | N/A | N/A | N/A |
| | **b. Width of staircase** | | | |
| | • Upper floors (Mezzanine) | 1.10 & 1.45 mtr. | 1.10 & 1.45 mtr. | MR |
| | • Basements | N/A | N/A | N/A |
| | **c. Protection of exits** | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Pressurization | N/A | N/A | N/A |
| | **d. No. of continuous staircase to terrace** | N/A | N/A | N/A |
| | **e. Width of corridor** | N/A | N/A | N/A |
| | **f. Door size** | 1.50 mtr. | 1.50 mtr. | MR |
| 3. | **Compartmentation** | | | |
| | • Fire check door | N/A | N/A | N/A |
| | • Sealing of electrical shafts | N/A | N/A | N/A |
| | • Fire rating of shaft door | N/A | N/A | N/A |
| | • Water curtain | N/A | N/A | N/A |
| | • Fire Dampers | N/A | N/A | N/A |
| 4. | **Smoke Management System** | | | |
| | • Basements | N/A | N/A | N/A |
| | • Upper floors | Required | Provided Natural | MR |
| 5. | **Fire Extinguishers** | | | |
| | • Total numbers | 04 nos. | 04 nos. | MR |
| | • Types | ABC/$CO_2$ | ABC/$CO_2$ | MR |
| | • ISI marking | Required | Provided | MR |
| 6. | **First-Aid Hose Reel** | | | |
| | • Total number of each floor | 01 no. | 01 no. | MR |
| | • Length of hose reel hose | 30 mtr. | 30 mtr. | MR |
| | • Nozzle diameter | 5mm | 5mm | MR |

| | | | | |
|---|---|---|---|---|
| | • Type of detectors | Required | Provided | MR |
| | • Location of main panel | Required | Provided | MR |
| | • Location of repeater panel | N/A | N/A | N/A |
| | • Alternate source of power | Required | Provided | MR |
| | • Hooter's Location | N/A | N/A | N/A |
| 8. | **MOEFA** | Required | Provided | MR |
| 9. | **Public Address System** | N/A | N/A | N/A |
| 10. | **Automatic Sprinkler System** | | | |
| | • Basement | N/A | N/A | N/A |
| | • Upper Floors | N/A | N/A | N/A |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | **Internal Hydrants** | | | |
| | • Size of riser/down-comer | N/A | Provided | N/A |
| | • Number of hydrants per floor | N/A | Provided | N/A |
| | • Hose box per floor | N/A | Provided | N/A |
| 12. | **Yard Hydrants** | | | |
| | • Total number of hydrants | N/A | N/A | N/A |
| | • Hose box | N/A | N/A | N/A |
| 13. | **Pumping Arrangement** | | | |
| | Ground level | | | |
| | • Discharge of main pump | N/A | N/A | N/A |
| | • Head of main pump | N/A | N/A | N/A |
| | • Number of main pumps | N/A | N/A | N/A |
| | • Jockey pump out put | N/A | N/A | N/A |
| | • Jockey pump head | N/A | N/A | N/A |
| | • Stand by pump output | N/A | N/A | N/A |
| | • Stand by pump head | N/A | N/A | N/A |
| | • Auto starting/Manual stopping | N/A | N/A | N/A |
| | Terrace level | | | |
| | • Discharge of pump | 450 LPM | 450 LPM | MR |
| | • Head of pump | 40 mtr. | 40 mtr. | MR |
| | • Power supply | Required | Provided | MR |
| | • Auto starting of pump | Required | Provided | MR |
| 14. | **Captive Water Storage for Fire Fighting** | | | |
| | • Underground tank capacity | N/A | N/A | N/A |
| | • Draw-off connection | N/A | N/A | N/A |
| | • Fire service inlet | N/A | N/A | N/A |
| | • Access to tank | Required | Provided | MR |
| | • Overhead tank capacity | 5,000 Ltrs | 5,000 Ltrs | MR |
| 15. | **Exit Signage.** | Required | Provided | MR |
| 16. | **Provision of Lifts.** | | | |
| | • Pressurization of lift shaft | N/A | N/A | N/A |
| | • Pressurization of lift lobby | N/A | N/A | N/A |
| | • Communication in lift car | N/A | N/A | N/A |
| | • Fireman's switch | N/A | N/A | N/A |
| | • Lift signage | N/A | N/A | N/A |
| 17. | **Stand by Power Supply** | Required | Provided | MR |
| 18. | **Refuge Area** | | | |
| | • Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |
| 19. | **Fire Control Room** | | | |

| | | | | |
|---|---|---|---|---|
| | • Flow switch panel | N/A | N/A | N/A |
| | • PA system panel | N/A | N/A | N/A |
| | • Battery backup | N/A | N/A | N/A |
| | • Building floor plan | N/A | N/A | N/A |
| 20. | **Special Fire Protection System for Protection of special Risk, if any:** | | | N/A |

*PNF – Provided but Non-Functional, *MR – Meeting Requirement, *NMR – Not Meeting Requirement

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, if approved, we may renew the FSC issued vide letter No. F6/DFS/MS/EH/NDZ/2023/148 dated 11.05.2023 to the Restaurant for Ground Floor only. The last date for deemed approval is **28/06/2026**.

Accordingly, **DFA** is prepared and put up for perusal and signature please.

BPrakash 22/6/2026
Bhupender Prakash
ADO (ND)

DO (NDD/ODD)
Sandeep 22/6/2026

CFO (EEN)
23/6/26

Principal Director

24/06/26

CFO (EEN)
25/6/26

ADO/ND
AS approved FoTo letter is put up for signature pls.
BPrakash 09/7/2026

Pl. speak.

CFO (EEN)
9/7/26